कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, झंझारपुर ।

पत्रांक 1259/अ० झंझारपुर / दिनांक 24/06/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, झंझारपुर ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
–सह– सचिव
ग्रामीण कार्य विभाग,
पटना।

विषय : शीर्ष 3054MR योजना अंतर्गत बिहार ग्रामीण पथ अनुरक्षण नीति – 2018 के तहत स्वीकृत कार्यों के आवंटन की मांग के संबंध में।

प्रसंग : भवदीय पत्रांक मु०अ०–4 (मु०)–3054–04–251/2018 – 113 अनु पटना दिनांक 10.01.2020

महाशय,

उपरोक्त विषयक प्रासांगिक पत्र के आलोक में शीर्ष 3054 MR योजना अंतर्गत बिहार ग्रामीण पथ अनुरक्षण नीति – 2018 के तहत स्वीकृत कार्यों में कृत कार्य के भुगतान हेतु विहित प्रपत्र में अधियाचना तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जा रही है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु. – विहित प्रपत्र में अधियाचना प्रपत्र
बम्प इन्टिग्रेडर मशीन से लिया गया प्रतिवेदन

विश्वासभाजन
19/6/23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
झंझारपुर
19/6/23

Scanned with CamScanner

Form GFR 19- A

(See Government of India's Decision (I) below Rule - 150)
Form of Utilazation Certificate upto the month June
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	1	85 enc/ Dt.14.06.2023	2270.38294	Certified that Rs:- 2270.38294 Lac received Till the date in favour of Executive Engineer, RWD Work Division Jhanjharpur. A sum of Rs.2130.61989 Lac has been utilized for the purpose of NEW_MR Scheme as given in the margin for which it was sanctioned and that the balance of Rs 139.76305 Lacs remaining .
		Total :	**2270.38294**	

Certifed and verified myself that the conditions on which the grands in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

i Works have been supervised by Executive Engineer/ Superintending Engineer.
ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
iii Construction material have been tested.
iv Measurments have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
v All other codal formalities have been observed.

Physical Progress achieved :-

i Construction of Road works.
ii Construction of CD works

19/6/23
D.A.O
RWD Works Division
Jhanjharpur

19/6/23
Executive Engineer
RWD works Division
jhanjharpur
19/6/23

Scanned with CamScanner

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division :Jhanjharpur

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Alloted Amount (I Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (In lac)										
1	RM/MAJHA/22/0009	Bhokharah a Patti tol to Raiyam West RCD Road tak	319981896106	1590/30.03.2022	2.400	257.28000	233.29844	30.05053	18SBD/22-23Dt:-20-10-2022	19-10-2023	1	3534.00	25mm	5.0%	0.00000	0.00000	228.83669	Completed
																	228.83669	

D.A.O
RWD Works Division
Jhanjharpur

19/6/23

Executive Engineer
RWD Works Division
Jhanjharpur

19/6/23

Scanned with CamScanner

Name of Customer: Pravin Kumar Mishra , Machine no: 19198 , Road: Pravin Kumar Mishra , Date: 15-06-23 , Section No: 55 , Equation: Y=1.0216X+165.9



15/6/23

15/6/2023

15/6/23

Scanned with CamScanner

Name of Customer: Pravin Kumar Mishra , Machine no: 19198 , Road: Pravin Kumar Mishra , Date: 15-06-23 , Section No: 55 , Equation: Y=1.0216X+165.9



15/6/23

15/6/23

15/6/23

Scanned with CamScanner

Name of work :	Bhokharaha patti Tol To Raiyam West RCD Road tak
Name of customer :	Pravin Kumar Mishra

(R)Rural Road		
Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
15/06/23	17:59:32	55	100	100	27.0 cm	1.8 Km/Hr	2700.0 mm/Km	2924	3.94	Good	26.2799240	N	86.2258821	E	Normal
15/06/23	18:00:01	55	100	200	22.0 cm	12.6 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.2804351	N	86.2267000	E	Normal
15/06/23	18:00:44	55	100	300	26.0 cm	8.2 Km/Hr	2600.0 mm/Km	2822	3.81	Good	26.2766462	N	86.2076427	E	Normal
15/06/23	18:01:21	55	100	400	25.0 cm	9.9 Km/Hr	2500.0 mm/Km	2720	3.69	Good	26.2799245	N	86.2258820	E	Normal
15/06/23	18:01:59	55	100	500	26.0 cm	9.4 Km/Hr	2600.0 mm/Km	2822	3.81	Good	26.3221052	N	86.2634530	E	Normal
15/06/23	18:03:09	55	100	600	22.0 cm	5.1 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.2798057	N	86.2227611	E	Normal
15/06/23	18:03:43	55	100	700	25.0 cm	10.6 Km/Hr	2500.0 mm/Km	2720	3.69	Good	26.2795712	N	86.2217462	E	Normal
15/06/23	18:04:17	55	100	800	27.0 cm	10.6 Km/Hr	2700.0 mm/Km	2924	3.94	Good	26.2785949	N	86.2202521	E	Normal
15/06/23	18:04:43	55	100	900	23.0 cm	13.5 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.2783329	N	86.2192382	E	Normal
15/06/23	18:05:04	55	100	1000	21.0 cm	16.8 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.2779672	N	86.2181688	E	Normal
15/06/23	18:05:28	55	100	1100	23.0 cm	15.5 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.2778812	N	86.2170478	E	Normal
15/06/23	18:06:04	55	100	1200	22.0 cm	9.8 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.2780446	N	86.2161675	E	Normal
15/06/23	18:06:33	55	100	1300	25.0 cm	12.6 Km/Hr	2500.0 mm/Km	2720	3.69	Good	26.2784866	N	86.2133696	E	Normal
15/06/23	18:07:11	55	100	1400	22.0 cm	9.3 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.2785181	N	86.2120869	E	Normal
15/06/23	18:07:34	55	100	1500	21.0 cm	15.4 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.2785185	N	86.2120877	E	Normal
15/06/23	18:08:11	55	100	1600	24.0 cm	9.6 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.2785583	N	86.2120891	E	Normal
15/06/23	18:08:34	55	100	1700	27.0 cm	15.7 Km/Hr	2700.0 mm/Km	2924	3.94	Good	26.2788651	N	86.2120897	E	Normal
15/06/23	18:09:11	55	100	1800	21.0 cm	9.7 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.2788655	N	86.2120905	E	Normal
15/06/23	18:09:33	55	100	1900	23.0 cm	16.5 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.2788668	N	86.2120998	E	Normal
15/06/23	18:09:55	55	100	2000	21.0 cm	16.2 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.2745219	N	86.2072255	E	Normal
15/06/23	18:10:32	55	100	2100	27.0 cm	1.8 Km/Hr	2700.0 mm/Km	2924	3.94	Good	26.2719931	N	86.2091116	E	Normal

Scanned with CamScanner

Name of work :	Bhokharaha patti Tol To Raiyam West RCD Road tak
Name of customer :	Pravin Kumar Mishra

(R)Rural Road		
Good	Average	Poor
< 4000	4001 - 5000	> 5000

15/06/23	18:11:01	55	100	2200	24.0 cm	12.6 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.2719936	N	86.2091119	E	Normal
15/06/23	18:11:44	55	100	2300	23.0 cm	8.2 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3320879	N	86.2634908	E	Normal
15/06/23	18:12:05	55	100	2400	23.0 cm	8.2 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3320879	N	86.2634908	E	Normal

15/06/23

15/6/2023 AE

15/6/23

Scanned with CamScanner