Name of work - Madhya Bidyalay Akbarpur Bank village
to Ho. Jan toda Sajahi Ghat (9)

Schedule XLV-Form No -134

AKBARPUR BAINK

M.M.G.S.Y.

~~BAINK~~ - SC

Bisauli

DIVISION

PT48230

Bisauli

SUB-DIVISION

Ag. No - 74/S.B.D/17-18 MB No - 887

MEASUREMENT BOOK

F. PARVEEN ALAM

1st year

Sch. XLV-Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
	Abstract of cost				
	— x — x —				
① Restoration of Retwalls P/70		104.00 m³			
	@ 358.87	=			37322/-
② Stripping excess Soil P/71		= 577.97 m²			
	@ 54.16	=			31303/-
③ Pr. Patch Repair of Pot holes P/71		= 47.54 m²			
	@ 112.45	=			5346/-
④ Pr. Patch Repair of B.T Surface P/72		= 48.16 m²			
	@ 100.92	=			4860/-
⑤ Maintenance of H.P. Culvert P/72		= 04 Nos			
	@ 1067.89	=			4272/-
⑥ Maintenance of Slab Culvert P/72		04 Nos			
	@ 2200.02	=			8800/-

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
(7) Cutting of tree branches					
P/72		= 08	Nos		
	@	99.67	=		498/-
(8) Cutting of shrubs					
P/72		= 21	Nos		
	@	6.12	=		129/-
(9) White washing of Parapet c/d walls					
P/72		= 83.20	m^2		
	@	15.55	=		1294/-
					93926/-
Less - 10% below					(+) 9393/-
					84533/-

Materials

(1) Earth work soil = 104 m^3

(2) Chips = 2.00 m^3

(3) Dust = 0.60 m^3

Approx 01/03/23

J. B.