# कार्यपालक अभियंता का कार्यालय,
## ग्रामीण कार्य विभाग, कार्य प्रमण्डल,झाझा।

पत्रांक 901 (अनु०) । झाझा दिनांक 16/5/24 ।

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल– झाझा।

सेवा में,

नोडल पदाधिकारी
नई अनुरक्षण नीति 2018(MR 3054)
ग्रामीण कार्य विभाग, बिहार पटना।

विषयः– शीर्ष नई अनुरक्षण नीति 2018(MR 3054) अंतर्गत राशि की अधियाचना के संबंध में।

महाशय ,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष नई अनुरक्षण नीति 2018(MR 3054) अंतर्गत कार्य की अद्यतन स्थिति के अनुसार अधियाचना वाछित प्रपत्र मे तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

अतः अनुरोध है कि आवंटन विमुक्त करने की कृपा की जाय ताकि संवेदक को ससमय भुगतान की जा सके।

अनु0:–यथोक्त।

विश्वास भाजन

16.5.24

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल,झाझा।

16.5.24

# RWD Works Division, Jhajha (Dist :- Jamui)

## Requisition Format for Scheme Head- MR (3054) Under Bihar Rural Road " New Manitenance Policy 2018" (Initial Rectification and Surface Renewal)

Name of Division:- Jhajha

| .N | Package No. | Name of Road | Project ID as per MIS | Administrative Approval (A.A) Letter No. & Date | Administrative Approval (A.A) | | Agreement Amount (in Lakh) | | Agreement No. & Date | Date of Comletion as per Agreement | Actual Date of Completion | Value of IRI in MM/KM | Thickness of Bitumen Layer (in MM) | Value of Bitumen Content (in %) | Previous Total Alloted Amount (in Lakh) | Up-to -date expenditure as per MIS (in Lakh) | Requisition against work done (in Lakh) | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | Length (K.M) | Amount (in Lakh) | Initial Rectification with Surface Renewal (in Lakh) | 5 Year Routine Maintenance | | | | | | | | | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 |
| 1 | RM/JA/JHA/23/0003 | Jamui road to Mahuli Village | 20804201017 | 08.09.2022 | 2.740 | 144.626 | 96.47201 | 26.17211 | 24/MBD/MR-N/2022-23 | 19.11.2023 | 09.10.2023 | 3120 | 25 | 5 | 71.20976 | 71.20976 | 7.11039 | Completed |
| 2 | RM/JA/JHA/23/0003 | Giddhaur Maura REO Road via Utkramit Middle School, Patsanda More to Kandhaura Road. | 20804201004 | 754 & 26.07.2022 | 1.2 | 70.996 | 52.65089 | 8.90597 | 24/MBD/MR-N/2022-23 | 19.11.2023 | 02.11.2023 | 3303 | 0 | 0 | 51.99535 | 51.99535 | 0.35915 | PCC in Whole length |

16.5.24

16.5.24

Executive Engineer
RWD Works Division, Jhajha

# FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150

Form of Utilization Certificate up to the month- 16 May 2024

New Maintenance Policy 2018 (MR 3054)

PIU – R.W.D. Works Division Jhajha

| SL. No. | Name of Scheme | Sanction No. & Date with | Amount Received (in Lacs Rs.) | Particulars |
|---|---|---|---|---|
| 1. | Construction of Rural Roads under New Maintenance Policy 2018 (MR3054) | Letter No-69 Dated- 06.05.2024 | 14008.87258 | Certified that out of Rs. 14008.87258 Lakhs received upto the years 24-25 in favour of Ex. Engineer, RWD Bihar. Jhajha a sum of Rs 0.00 lakhs has been utilized for the purpose of New Maint. Policy 2018 (MR3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 0.00 lakhs remaining unutilized at the end of the period . |
| | Total | | 13847.50747 | |

2. Certified that I have satisfied may self that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Cheeks exercised-

i. Works have been supervised by Executive Engineer/Superintending Engineer
ii Periodical inspection has been conducted by Executive engineer/Superintending Engineer
iii Construction materials have been tested.
iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer
v. All other codal formalities have been observed.

3. Physical Progress achieved-

i. Construction of Road Works Construction of C.D. Works .

16.5.24

D.A.
RWD(w) Div. Jhajha

16.5.24

Executive Engineer
RWD(w) Div. Jhajha

**Name of Road-Construction Of Roads from Jamui road to Mahuli Village**

**Name of Agency-Arvind Singh**

| Date | Time | Section | Length | Bumps | Speed | OR | IRI | CATEGORY | Latitude | Longitude | Event |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | No. | in km | in mm | Rate | mm/km | mm/km | ROAD | | | |
| 3/9/23 | 16:2:31 | 72 | 0.1 | 310 | 10.1 | 3100 | 2908 | G | 24.870372 | 86.29808 | Normal |
| 3/9/23 | 16:3:5 | 72 | 0.1 | 280 | 10.1 | 2800 | 2659 | G | 24.870685 | 86.297137 | Normal |
| 3/9/23 | 16:4:0 | 72 | 0.1 | 340 | 10.1 | 3400 | 3156 | G | 24.870727 | 86.29616 | Normal |
| 3/9/23 | 16:4:15 | 72 | 0.1 | 290 | 10.1 | 2900 | 2742 | G | 24.870912 | 86.295185 | Normal |
| 3/9/23 | 16:5:0 | 72 | 0.1 | 400 | 10.1 | 4000 | 3653 | G | 24.871035 | 86.294192 | Normal |
| 3/9/23 | 16:6:1 | 72 | 0.1 | 420 | 10.1 | 4200 | 3819 | G | 24.8707 | 86.293282 | Normal |
| 3/9/23 | 16:6:37 | 72 | 0.1 | 350 | 10.1 | 3500 | 3239 | G | 24.87028 | 86.292558 | Normal |
| 3/9/23 | 16:7:12 | 72 | 0.1 | 270 | 10.1 | 2700 | 2577 | G | 24.870528 | 86.291615 | Normal |
| 3/9/23 | 16:7:15 | 72 | 0.1 | 260 | 10.1 | 2600 | 2494 | G | 24.870657 | 86.290622 | Normal |
| 3/9/23 | 16:8:0 | 72 | 0.1 | 300 | 10.1 | 3000 | 2825 | G | 24.870943 | 86.289697 | Normal |
| 3/9/23 | 16:8:22 | 72 | 0.1 | 270 | 10.1 | 2700 | 2577 | G | 24.871537 | 86.288972 | Normal |
| 3/9/23 | 16:8:58 | 72 | 0.1 | 320 | 10.1 | 3200 | 2991 | G | 24.872388 | 86.288703 | Normal |
| 3/9/23 | 16:9:0 | 72 | 0.1 | 340 | 10.1 | 3400 | 3156 | G | 24.873007 | 86.288047 | Normal |
| 3/9/23 | 16:9:33 | 72 | 0.1 | 300 | 10.1 | 3000 | 2825 | G | 24.87339 | 86.287103 | Normal |
| 3/9/23 | 16:10:8 | 72 | 0.1 | 250 | 10.1 | 2500 | 2411 | G | 24.873732 | 86.286228 | Normal |
| 3/9/23 | 16:11:0 | 72 | 0.1 | 290 | 10.1 | 2900 | 2742 | G | 24.874082 | 86.285285 | Normal |
| 3/9/23 | 16:11:19 | 72 | 0.1 | 420 | 10.1 | 4200 | 3819 | G | 24.874702 | 86.284915 | Normal |
| 3/9/23 | 16:12:29 | 72 | 0.1 | 360 | 10.1 | 3600 | 3322 | G | 24.875573 | 86.28513 | Normal |
| 3/9/23 | 16:13:5 | 72 | 0.1 | 390 | 10.1 | 3900 | 3570 | G | 24.876403 | 86.28547 | Normal |
| 3/9/23 | 16:13:40 | 72 | 0.1 | 430 | 10.1 | 4300 | 3901 | G | 24.877188 | 86.28508 | Normal |

Y = 0 * X ^ 2 + 0.828 * X + 341.6

X = 4286

Y = 3890

(R) RURAL ROAD

| Good | Average | Poor |
|---|---|---|
| <4000 | 4001-5000 | >5001 |

Error



Scanned with CamScanner

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3/ 9/ 23 | 16: 14: 0 | 72 | 0.1 | 400 | 10.1 | 4000 | 3653 | G | 24.876755 | 86.284275 | Normal |
| 3/ 9/ 23 | 16: 14: 15 | 72 | 0.1 | 350 | 10.1 | 3500 | 3239 | G | 24.877078 | 86.28335 | Normal |
| 3/ 9/ 23 | 16: 14: 25 | 72 | 0.031 | 380 | 10.1 | 3800 | 3487 | G | 24.877093 | 86.283215 | Normal |
| | | | | | | **Total** | **3120** | | | | |

Bikash
3-9-23
J.E.

01/11/23



Scanned with CamScanner

| | |
|---|---|
| Name of Customer : | Arvind Singh |
| Name of Work/ Road : | Jamui road to Mahuli Village |
| Lab Job number | 72 |
| Date : | 9 / 3 /2023 |
| Section No. | 72 |

| | | | |
|---|---|---|---|
| Test Date : | 9 / 3 /2023 | Road Name : | Jamui road to Mahuli Village |
| Machine No : | 435 | Road Type : | (R) RURAL ROAD |
| Start S No : | | Side : | |
| Start E No : | | | |
| Weather : | | UIV Range : | 1411 To 5000 Interval 1000 mm/km |
| Start Location : | | Dist Range : | 0 To 2.4 0.1 * 1000 m |
| End Location : | | Equation : | Y = 0 * X ^ 2 + 0.828 * X + 341.6 |

Print | Generate Report and Graph | Redraw Graph | Map View

Section No. :72, Eqn : Y = 0 * X ^ 2 + 0.828 * X + 341.6

Name of Customer :. Name of Work/ Road :. Lab Job number :




Jeewar
3-9-23
JE.

1/11/23