| Particulars | Details of actual measurement | | | | Contents of area |
|---|---|---|---|---|---|
| | No. | L. | B. | D. | |
| | 3rd year maintenance | | | | |
| Name of work — Maintenance of Road from Harpur Rewari Path to Harijan tola under Virar Pur Block | | | | | |
| Agy — chalardhar chaudhary | | | | | |
| Ad No — 648 BD/2019-20 | | | | | |
| Date Comd — 5.3.2021 | | | | | |
| Date Comp — 8/3/2024 | | | | | |
| ① Restoration of Berm cut & | | | | | |
| Mus all Completes — | | | | | |
| 10 x 15m x 1m x .30 = 45 m3 | | | | | |
| 10 x 15m x .90 x .30 = 40.5 m2 | | | | | |
| 16 x 15m x .75 x .30 = 54.00 | | | | | |
| 139.5 m3 | | | | | |
| Lum 138.348 m3 | | | | | |
| 2 making up of Berms | | | | | |
| Shulder mus all Completes — | | | | | |
| 2 x 10 x 15m x 1m = 300 m2 | | | | | |
| 2 x 10 x 15m x .75 = 225 m2 | | | | | |
| 2 x 10 x 15m x .60 = 180 m | | | | | |
| 1 x 13m x .60 = 7.80 | | | | | |
| 712.80 m2 | | | | | |
| 3. Repair of pot holes | | | | | |
| filled mus 75mm thm. | | | | | |
| 8 x 4m x 2.00 x .075 = 4.80 m3 | | | | | |
| 6 x 3m x 1.50 x .075 = 2.025 | | | | | |
| 5 x 2.50 x 1.20 x .075 = 1.575 m3 | | | | | |
| 8.40 m3 | | | | | |

Continuation

Sch. XLV-Form No. 134

| Particulars | Details of actual measurement | | | | Contents of area |
|---|---|---|---|---|---|
| | No. | L. | B. | D. | |
| | | | | B/F | 237360= |
| 8 / 12 A/B | Cost of Road Marking | | | | |
| | including all Completions | | | | – |
| Pushpa Sanitary | | | B | 33 | |
| 8A (8) | | | | | |
| (8) BT Asem | | | 320 | m2 | |
| @ Rs 850.93/m2 | | | | | Rs 272298= |
| b.e.c. Asem | | | 70.40 | m2 | |
| @ Rs 953.99/m2 | | | | | Rs 67161= |
| | | | | | Rs 576819= |
| | | | 8/3/2024 | | |