Sch. XLV—Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
	2nd yr Maintance				
Name of work – Construction of road from Gaurav Rajpurohit Path to Kuttar Pal (Agra Puri Sil) Path Sa. Kher Gotra Parod Tola Sh 66 purana Khas Tak.					
Name of Agency – Sri Amit Kumar Singh					
Agr. No :-					
Date of Commencement – 09.03.2019					
Date of Completion – 08.03.2020					
Actual Completion – 05.03.2020					
Date of Entry – 04.03.2020.					
	Item of Work.				
I.No.1:-	Restoration of Rain cuts/ Berms with soil mortum et - Comp - 4%.				
	4	x 2 x	30 x	0.86 x 0.30 =	61.92 M³
	3	x 2 x	30 x	0.77 x 0.30 =	41.58 M³
					103.50 M³
				@ -	103.28 M³
I.No.2:-	Making c/s (berms/ shoulders, stripping excess soil from the shoulder etc				
	4	x 2 x	30 x	1.10 =	264.00
	1	x 2 x	30 x	0.65 =	39.00
					303.00 M³

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
S.No.03/05 – Patch repair (Non bituminous surface with 20 mm thick premix surface etc. complete)					
	2	3.10	1.32	=	10.664
	2	8.15	1.32	=	21.516
	2	5.00	1.00	=	10.000
					42.784 m²
S.No.04/07 – Maintenance of C/D works (Minor bridge/culvert)					04 Nos.
S.No.05/09 – Maintenance of Roads/Streets vide S.No. 01 of Annexure-I					0.20 km
S.No.06/10 – Maintenance of 300 mm cement concrete kerb stones etc. complete.					0.26 km
S.No.07/11 – Trimming of Branches of trees and shrubs.					02 Nos.
S.No.08/12 – White washing of Retaining walls of C/D works etc.					
	4	2 x 6.05	1.62	=	78.408
	4	2 x 6.05	0.40	=	19.360
					97.768 m²
					84.00 m²

04/03/2022

4/3/22

Sch. XLV—Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
Material Statement —					
(1) Earth —		103.284	3	0.68 = 344	
(2) Crushed Stone aggregate -		1.144	3	408 = 674	
(3) Crushed Sand —		0.254	3	90 = 274	
24/03/22					
Bitumen Statement —					
(1) Bitumen emulsion —		0.0504 T.			
(2) Bitumen 80/100 —		0.2274 T.			
24/03/22					

Abstract of Cost

4.40.1:-	Restoration of section of -- Comp. etc.:				
	Vide P.No. 36 in T.4.B.				
103.28			3	365 = 25	37723=00
4.40.02	Making up Berms / Shoulder Stipping etc.				
	Vide P.No. 36 in T.4.B.				
303.00			1/2	54 = 164	16410=0
4.40.03/05	Patch repair Overlaid Surface with 20 mm Premix Surface of 4 cm				
	Vide P.No. 37 in T.4.B.				
42.18			1/2	321 = 514	13561=00
					Q — 67694=00

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
					R- 67694=00
4.20.04/89	Maintenance C/T work (Thrope pipe Culvert)				
	Vide P-40 37 in T-4-B.				
04 Nos	R- 1131=64				R- 4527=00
4.20.05/09	Maintenance of Road Sign				
	Vide P-40. 37 in T-4-B.				
0.20 Km	R- 1087=62			/Km R-	218=00
4.20.06/10	Maintenance of 200 mtr Km Stones.				
	Vide P-40 37 in T-4-B.				
0.26 Km	R- 654=33			/Km R-	170=00
4.20.07/11	Cutting of ~~Bushes~~ of trees & Grass etc.				
	Vide P-40 37 in T-4-B				
02 Nos	R- 107=48½			Each R-	215=00
~~84.004~~	~~R- 16=48 4~~			R-	~~1384=00~~
4.20.08/12	White washing of Road side walls of C/T work etc.				
	Vide P-40. 37 in T-4-B				
84.004	R- 16=48 4½			4½ R-	1384=00
				R-	74208=00
	Less 10% Below			R-	7421=00
				R-	66787=00

04/03/2022
J.E. Mathura

4/3/22