RRSMP (SC) M.M.U S.L.Y

Name of Road – Barco govindpur Road to bela

Shedule XLV Form No. 134.

DIVISION

CNS-ESM(JV)

SUB-DIVISION

আভিমুখ

Measurement Book

M.B.No – (1620)

1st on R/A bill

1.

Name of work -
Situation of work -
Agency by which work is executed -
Date of measurement -
No. and date of agreement.
(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work - maintenance of Road Bayeo Govindpur Road to Bela.					
2. M/S Niranjan Sharma NS-ESM(JV) At-Nishigama Belan Bazar (Nawada)					
3. Agg. No - 03/MM/SUY/RRSMP/ CMBD-2025-26 Rajauli					
4. Name of Pakage - RRSMP/24-25 Rajauli/02					
5. Date of commencement 23/09/2025					
Record Entry					
1, Clearing and Grubbing Road Land (By manual means) including uprooting wild vegetation de-de.					
2X2X	30.0	X1.0	= 120.00		
2X2X	30.0	X1.0	= 120.00		
			240.00		

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
			240	.00	
2X1X	300	X 1.0	= 60.	00	
2X3X	30.0	X 1.0	= 180	.00	
2X3X	30.0	X 1.0	= 180	.00	
2X1X	20.0	X 1.0	= 40	.00	
2X2X	30.0	X 1.0	= 120	00	
2X1X	20.0	X 1.0	= 40	.00	
2X4X	30.0	X1.0	= 240	.00	
2X4X	30.0	X1.0	= 240	.00	
2X6X	30.0	X1.0	= 360	.00.	
2X3X	30.0	X1.0	= 180	.00	
2X4X	30.0	X1.0	= 240	.00	
2X1X	30.0	X1.0	= 60.	00	
2X	1X10.0	X	1.0 =	20.00	
				2200.00	
	0.22 Ha				
2. const. of un-reinforced plain cement conc. pavement (M35 Grade) over a prepared sub-base --do--do. in profile correction Pot repair					
1	1X2.20	X1.40	X 0.1	= 0.308	
1	1X2.66	X 2.90	X 0.1	= 0.771	
2	2X3.10	X1.70	X 0.1	= 1.054	
2	2X1.50	X1.20	X 0.1	= 0.360	

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure No.	L.	B.	D.	Contents of area
2 X	3.10 X	1.65	X 0.1 =	1.023	
1 X 2.	45 X	2.10 X	0.1 =	0.515	
2 X	2.30 X	1.30 X	0.1 =	0.598	
2 X 1.	20 X 0.	90 X	0.1 =	0.216	
1 X 2.	74 X	1.59 X	0.1 =	0.436	
3 X 1.	21 X	1.70 X	0.1 =	0.617	
1 X 2.	56 X	1.80 X	0.1 =	0.461	
				~~5.355~~ m³ 6.358 m³	
POC Pavement					
1 X 30.0 X	3.70 + 3.77 + 4.30 / 3		X 0.1 =	11.770	
1 X 30.0 X	4.30 + 3.30 / 2		X 0.1 =	11.40	
1 X 30.0 X	3.30 + 3.70 / 2		X 0.1 =	10.50	
1 X 30.0 X	3.70 + 3.10 / 2		X 0.1 =	10.20	
Pavt B					
1 X 30.0 X	5.40 + 3.65 / 2		X 0.1 =	13.575	
1 X 21.0 X	3.65 + 3.80 + 3.35 / 3		X 0.1 =	7.560	
Pavt C					
1 X 30.0 X	2.70 + 4.35 + 4.20 / 3		X 0.1 =	11.250	
1 X 30.0 X	4.20 + 3.0 + 4.80 / 3		X 0.1 =	12.00	
1 X 30.0 X	4.80 + 3.65 + 3.15 + 4.85 / 4		X 0.1 =	12.338	
1 X 30.0 X	4.85 + 3.30 + 3.75 / 3		X 0.1 =	11.900	
1 X 13.0 X	3.75 + 3.30 + 3.75 / 3		X 0.1 =	4.680	
				123.531 m³	

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
3. Providing and fixing 1 etgo of mm Grisuy intermalay sign board.					
2. ONO					
Jayawal 24/11/25 J.E					

29/11/25 A.E.

Material statements

coarse sand = 55.539
crushed stone = 111.178 m3
Cement = 49.412 MT
Admixture = 247.062 Kg

Jayawal
24/11/25
J.E

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure No.	L.	B.	D.	Contents of area
B.	Abstract of cost				
1 Clearing and Grubbing Road land (By manual means) including Uprooting wild vegitation.					
do do					
Qty. vide TMB P.No. 2(1) 0.22 Ha @ 73248.75/Ha				=	16115=00
2. Const. of un-reinforced plain cement conc. (M35 Grade) over a prepared sub base.					
Qty vide TMB P.No - 3(2) 123.53 m^3 @ 5691.09/m^3				=	703026=00
3. P/U and fixing Logo of Mysuru Mahanagara sign board.					
Qty - vide TMB P.No - 4(3) 2 No - @ 10569.35/No				=	21139=00
					740280=00
Add 1%	L.C			=	7403=00
Add 18 % G.S.T.				=	133250=00
Add	S.F			=	13406=00
					894339=00
Less.	15.10 % below			(−)	135045=00
					759294=00

Jayaveer 24/11/25 J.C

Continuation

24/11/25 A.E.