

21242-4104-254

MR3054 25 319<2016A

-2018

MA04-2264

Schedule XLV-Form No. 134

2018 25 319<2016A

DIVISION

SUB-DIVISION

Measurement Book

(3)
Record Book

1

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Construction of Road					
Bed course & maintenance					
for Pachayano, M.C.N. 119/					
Munafar per G.M.T. 01/02					
Bamauli to Gorigau, fall					
Agency: R.P.M. Surnagar, Ray					
Assess. 110 New Road 2019-20					
Date of Comm. 10/10/19					
Date of Completion: 9/7/20					
Item 1/ cleaning & grading Road bed & Tse.					
$2 \times 81 \times 30.00 \times 1.00 / 10000 =$					0.486
$2 \times 1 \times 10.00 \times 1.00 / 10000 =$					0.002
				Total	0.488
Item 2/ securing the existing boundaries					
Road - Tse.					
$4 \times 30.00 \times 3.75 =$					450.00
$1 \times 3.00 \times 3.75 =$					11.25
				Total	461.25
Item 3/ Construction of boundary					
Sub-bank by G.M.T.					

Continuation

14

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item 1) clearing 2 gumbaz Road at vide item no. (1) map (A) Qty = 0.498 ha @ 4929 m ² 1845					
Item 2) Surveying the existing lake vide item no. (2) map (A) Qty = 457.8000 m ² @ 12.5081 m ² 8010					
Item 3) Locality G.R.S. II vide item no. (3) map (A) Qty = 41.1500 m ² @ 234.81 m ² 9776					
Item 4) Pore Bluing work vide item no. (4) map (A) Qty = 27.28100 m ² @ 4159.06 m ² 113463					
Item 5) Pore Bluing work vide item no. (5) map (A) Qty = 69.311 m ² @ 3962.51 m ² 274642					
Item 6) Pore Bluing work vide item no. (6) map (A) Qty = 924.1500 m ² @ 53.98 m ² 49886					
Item 7) Pore Bluing work vide item no. (7) map (A)					

Continuation

Q. 05 555572

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.F. 55572	
Qty = 1055.5002	2	18.16/m			18442
Item 1) Poor quality of SDB					
vide item no. (8) work (8)					
Qty = 250.6002	2	12891.93			2912529
Item 9) Poor thermoplastic paint					
vide item no. (9) work (8)					
(i) At edge = 488.0002					
(1) 850.93/m					415254
(ii) At crossing = 4.0002					
(1) 850.93/m					3404
Item 10) Cont. for ground work					
vide item no. (10) work (8)					
Qty = 1024.8002	2	189.60/m			194302
Item 11) Poor quality of grass					
vide item no. (11) work (8)					
Qty = 924.1500	2	252.88/m			233699
Item 12) Poor work on kerb					
vide item no. (12) work (12)					
Qty = 11.5200	2	6125.61			70567

Continuation

C.O. 24445677
4559552

C.O. ~~4563530~~
4677405

Scanned by CamScanner