


FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.750
Name of Road :NH- 28 Rupouli Panchyat Bhawan Se Mukhiya Shri Amarkant Choudhary Ke Ghar Tak		
Scheme / Programme: MAINTENANCE		
Package No:RM/SA/DAL/19/0002		Road Id No: 10105090
Status of the Project: Ongoing /Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	"S"
b)	Condition of Surfacing	"S"
c)	Riding Quality	"S"
d)	Road Camber	"S"
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES
f)	Constraction Joint provided or not(CC Pavement)	NO
g)	Compaction of flank/slope & raincuts if any	-
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	"S"
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES
4	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-


 02.12.2020
 (Signature)

NAME: Sri Jay Kishor Thakur
 DESIGNATION : Executive Engineer