## FIELD INSPECTION REPORT

Date of Inspection: 0'	3/12/2020	District: Madhusami	
Division: Thom jho	spur	Length (km): 2 1. 800 km	
		thi tol bhaya mithila deep.	
Scheme/Programme:			
Package No.: MR-N/19	1-20/shonjhorpor/03	Rond Id No.: 31909804017	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sli No.	Parameters to	be checked Remarks	
I. Pavement			

Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No on goime	
4.	Compliance History	U.	
a)	Status of ATR's & any others	20	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	ř,
Unsatisfactory (U)	

(Signature)

NAME:

DESIGNATION: