FIELD INSPECTION REPORT

Date of Inspection:	3.12.2020	District: SIWAN
Division: MAHAI	RAJGANJ	Length (km): 4.5 KM
Name of the Road:	ILLSAR 40 F	Bhikhampur path
Scheme/Programme:	MAINTENANCE	pain
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked		
1.	Pavement	Remarks	
a)	Road Junction condition	Ş/U	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
<u>f)</u>	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage Yos/No		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	3/(1

(Signature)

NAME: - Latyendra Harain Singa DESIGNATION: Assistant Engineer

Name - Dharmendra kuman Degianation - Junior Engineer