FIELD INSPECTION REPORT

| Date of | Inspection: 0. | 2.12.2020 Dis | trict: BANKA | |
|-------------------|--|-----------------------|----------------------|--|
| Division: Banka-1 | | | Length (km): 3.4 | |
| Name of | the Road: KI | resay Tompey Sila | ini Road (Pant) | |
| Scheme/ | r rogramme: | MAINTENANCE | | |
| Package | No .: RM/BA | BAN 19 0006 Ros | 14/20/2872:.oN bl bi | 5 |
| omitus U | i me r roject; | Ongoing/Completed/Und | er Maintenance | The state of the s |
| | Vork is a case of: New Connectivity/Up gradation/ Maintenance | | | |
| Sl. No. | 2329 | Parameters to be ch | ecked | Remarks |
| 1. | Pavement | | | |
| a) | Road Junction condition | | | |
| b) | Condition of Surfacing | | | |
| c) | 7 Publication and Market and American | | | √8/U |
| | Riding Quality | | | VS/U |
| d) | Road Camber | | | √S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. | Cross Drainage | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting &/SRI/U | | | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U | | | |
| c) | Condition of railings/slab/approach for Bridges | | | |
| 3. | Road Furniture Condition of railings/slab/approach for Bridges S/SRI/U | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Vés/No |
| 4. | Compliance History | | | |
| a) | Status of ATR's & any others | | | ET A SET OF |

Overall Rating :

| Satisfactory (S) | satisfactory (s) |
|----------------------------------|------------------|
| Satisfactory but requires Improv | ement (SRI) |
| Unsatisfactory (U) | |

Prifam 02 12 20 20 (Signature)

NAME: PRITAM KUMAR