

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Palna
Division : Palna Sampat	Length (km): 0.900 km.
Name of the Road: Khairatali Suryamandir to Dastijapur Brafeshwar market	
Scheme/Programme: MAINTENANCE - New Maintenance Policy (2018)	
Package No.: 12	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Work yet to start.
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage N/A	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History N/A	
a)	Status of ATR's & any others	Work yet to start.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: SUPRIYA RANI.

DESIGNATION: Assistant Engineer
RWD (Co) Sub-Division,
Sampatdak.