FIELD INSPECTION REPORT

Date of Inspection :	Blialan	District: Begusan	Maryon W.
Division: Balle.		Length (km): 1.750	
Nama of the Dat	H-31 Co 0.		****
Scheme/Programme:	MAINTENA	ice petral pump se awardh tirhul pute	Ta
Package No.:	and the second s	Road Id No.: 32010 608075	on September 1
Status of the Project:	Ongoing/Completed/Under Maintenance		Ti Angua
Work is a case of:	New Connectivity/Up gradation/ Maintenance		to the water of

work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked 5		
1.	Pavement		
a)) Road Junction condition		√\$/U
b)	Condition of Surfacing		√\$/U
c)	Riding Quali	₺ /U	
d)	Road Cambe	√S/U	
e)	Whether free aggregates in	Xes/No	
f)	Contraction J	Yes/No	
g)	Compaction	Xes/No	
2.	Cross Drain	age	
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/I		
b)	Condition of	S/SRI/U >	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether signstones/Pavem	Yes/No	
4.	Compliance	History	
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	-

NAME: Rameswar chaudhary

DESIGNATION: BE

(Signature) Executive Engineer RWD Works Division, Balla