

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Roheta
Division :	Bikramganj	Length (km):	4.100 km
Name of the Road:	SURPura bhayni dhgm Road to Navam Road		
Scheme/Programme:	MAINTENANCE	new maintenance Policy 2018	
Package No.:		Road Id No.:	1030100/054
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance policy 2018		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
f)	Contraction Joints provided or not (CC Pavement)	N.A
g)	Compaction of flank/slope & raincuts if any	NO too done
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No only sign board
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ravish
03/12/2020
(Signature)

NAME: Ravish Kumar