## FIELD INSPECTION REPORT

Date of Inspection:	4.12.20	District: W. Champaran	
Division: Bagaha-1		Length (km): 3.900 km	
Name of the Road: So	baiya Chowk	Murera via mahui Path	
Scheme/Programme:	MAINTENANCE	New Maint. Policy 2018 (MR-3054	
Package No.: RM/WIE/BAG/19/0001		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks	
1.	1. Pavement		
a)	Road Junction condition	<b>S/U</b>	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	<b>√</b> 8/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No-	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No~	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yés/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Deepak Kumar

DESIGNATION: J.E