Date of	Inspection: 6	3/12/2020 D	strict: West	chambo	man
Division: Bettient Length					
	of the Road: N	achtergawan fo	Lauriya via 0		9 Done
	Programme:	MAINTENANCE	0	0	0.0
Package No.: Status of the Project: Ongoing/Complete			Road Id No.: 31808808088		680
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sirkini	S lecial and a second state of	AND THE PERSON OF THE PERSON O	STANKEN SALASANSANSANSANSANSANSANSANSANSANSANSANSAN	TO THE WAY	Lomerto
i veti	Payement				
a)	Road Junction condition				S/U
b)	Condition of Surfacing				S/U
c)	Riding Quality				8/U
<u>d)</u>	Road Camber				8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
	A District to the same			Tare the or wets.	
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b) :	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
					in when the
a)	D				Yes/No
and the state of t	resignite di	THE CONSIDERATION AND A	是自己的		Plade
CATTO: & any others				No	
a)	Status of ATK's				•
March I	Patino :	(6)			S
Overall Rating		Satisfactory (S) Satisfactory but requires Improvement (SRI)			
	*		III es turbio.		
	•	Unsatisfactory (U)			

(Signature)

NAME: Ram Donlar chauter DESIGNATION: Junior Engineer