

FIELD INSPECTION REPORT

Date Of Inspection	2.12.2020	District	Bhojpur
Division - PIRo, Block - PIRo		Length (km):	7.415
Name of the Road:	Chak Tola- Bechena More Pathing Piliya Tola Lakhan Tola, 2 Rangs		
Scheme/Programme	MAINTENANCE		
Package No.:	RM1BH1PIR/19/0002	Road Id No.:	NEA 22000 1630
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked		Remarks
1	Pavement		work started
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m' stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Sushil Kumar

(Signature)
21/12/2020

Designation Junior Engineer