FIELD INSPECTION REPORT

Date of Inspection: 04/12/2020			District: Mo	42affarbur		
Division	: RWD WE	ST	Length (km):	2		
		inti Marwan - 1	Bheruyahi Pr	1654 Road	A 18 10 10 10 10 10 10 10 10 10 10 10 10 10	
	Programme:	MAINTENANCE				
		/MUZ/19/0022		VEA2200024	77	
Status of the Project: Ongoing/Completed/Un Work is a case of: New Connectivity/Up a					-	
SI. No. Parameters to be checked				Remarks		
	2	Kemarks				
1.	Pavement	established in the				
a)	Road Junction condition N/A.				S/U	
b)	Condition of Surfacing				S/U	
c)	Riding Quality NIA				S/U	
d)	Road Camber · N/A				S/U	
e)	Whether free aggregates in	Yes/No				
f)	Contraction Joints provided or not (CC Pavement)				Yes/No	
g)	Compaction of flank/slope & raincuts if any				Yes/No	
2.	Cross Drain	age			Washington Company	
a)	Condition of	S/SRI/U	NIA			
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	NH
c)	Condition of railings/slab/approach for Bridges				S/SRI/U	14/6
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					N
4.	Compliance History					
a)	Status of ATR's & any others				NO ATR	1

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Raman krishang

DESIGNATION: At