

NAME: Sundera Kumar
5.50 RWD
Chennai

(Signature)
Sundera Kumar
22/1/2020

Satisfactory (S)	N-App.
Satisfactory but requires Improvement (SRI)	"
Unsatisfactory (U)	"

Overall Rating :

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Work not started
a)	Road Junction condition	N/A
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Not app.
f)	Contraction Joints provided or not (CC Pavement)	Not app.
g)	Compaction of Bank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Work out
a)	Condition of head walls in Raine pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railing/slab approach for Bridges	S/SRI/U
3.	Road Furniture	N/A
d)	Whether sign boards/information, cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	Work not started
a)	Status of ATR's & any others	

Date of Inspection : 03-12-2020
Division : Trivendrum
Name of the Road : PARIATHI TO M.E.H.DIPUR
Scheme/Programme : MAINTENANCE
Package No. :
Status of the Project : (ongoing/Completed/Under Maintenance)
Work is a case of: New Connectivity/Up gradation/ Maintenance

Length (km): 8.4
District: Subaru