

NAME: S. D. S. Kumar
S.D. S. Kumar
R.W.D. Sub. Div. Changanassery

(Signature)
S. D. S. Kumar
09/12/20

Satisfactory (S)	N. Applicable
Satisfactory but requires Improvement (SRI)	"
Unsatisfactory (U)	"

Overall Rating :

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Work not started
a)	Road Junction condition	Not applicable
b)	Condition of Surfacing	Not applicable
c)	Riding Quality	Not applicable
d)	Road Camber	Not applicable
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Not applicable
f)	Contraction Joints provided or not (CC Pavement)	Not applicable
g)	Compaction of flank/slope & raincuts if any	Not applicable
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	N/A
4.	Compliance History	
a)	Status of ATR's & any others	

Date of inspection : 03-12-2020	Division : Trivandrum	District : Subaru
Name of the Road : Mirapatt to Bhavani Patti	Scheme/Programme : MAINTENANCE	Road Id No. :
Package No. :	Status of the Project : Ongoing/Completed/Under Maintenance	Work is a case of: New Connectivity/Up gradation/ Maintenance