

FIELD INSPECTION REPORT

Date of Inspection : - 09-12-2020 District: Samastipur
 Division : PWD Length (km): 0.330 KM
 Name of the Road: PWD Sadak Gupta Baidh Se Railway Ghala Tak
 Scheme Programme: MAINTENANCE MIMGSY
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ☒ S
b)	Condition of Surfacing	S/U ☒ U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒ No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRIA ☒ S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRIA ☒ N/A
c)	Condition of railings/slab/approach for Bridges	S/SRIA ☒ N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	No Any ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Ravi
 (Signature) 09-12-20

NAME: - Ravi Ranjan

DESIGNATION: J-E