		FIELD INSPECT	ION REPORT	
Date of Inspection-		09.12.2020	District Areria	
Division-		Araria	Length (KM) 5.20 K	cM
Name of Road-		Pategna chark to Sahasmal (Biri Pul)		
Scheme/Programme-		Maintenance		
Package no			Road Id No. MR 3054	
status of the Project		On going/Complete/Under Maintenance		
Vork is	a case of	New Connectivity/Up g	radation/Maintenance 🖊	
l no.		Parameters to be Checked		Remarks
1	Pavement			
a	Road Junction Condition			S/U ✓
b	Condition of Surfacing			S/U~
С	Riding Quantity			S/U~
d	Road Camber			5/U~
e	Whether free from defects such as visible cracks, exposed aggregates in Yes/No case of CC Pavement			Yes/No
f	Contraction joints provided or not (CC Pavement)  Yes/No			Yes/No
g	Compaction of flank/slope & raincuts if any  Yes/Now			
- 2	Delate			
a	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
Ь	Condition of Abutment & Wing walls, Slab in RCC Culverts			S/SRI/U
С	Condition of railings/slab/approach for Bridges  S/SRI/U			
3	Road Furniture			
а	Whether sign board/informatory/cautionary Board/KM & 200 m			
	stones/Pavement road markings are provided and maintained			
4	Compliance H		The second of the second	Marie San Company
а	Status of ATR's & any others			

Hote-Road condition is reported in FDR

Overall Rating:

_
_
U

Signature C.E-2

Name

Er. Yogeshwer Pandey Chief Engineer - 2