

FIELD INSPECTION REPORT

Date of Inspection : 12/12/20		District: Subur	
Division : Mbu		Length (km): 1.650	
Name of the Road: Shini to Bonnyan			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.: AR3504			
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

out of maintenance.
New MR

(Signature) 12/12/20

NAME: Jethava Kumar Singh
DESIGNATION: A.C, R.W.D.O. Subur - Subur
Subur, Subur - Subur