FIELD INSPECTION REPORT

Date	of Inspection:	12.12.20	District: East champaran	
And the second deposits and the second deposits of the second deposi		relitations 4 delegate may challenge the second second	Longth (km): 1.10 K M	
Nam	e of the Road: C	Lainpur (Paul	oka) to Solivani (BR-	11-07)
Schen	me/Programme:	MAINTENANCE	3037	The second secon
There is not the	age No.:		Road Id No.: 31708508	024
l	s of the Project:	Ongoing/Completed	I/Under Maintenance	Company of the Company of September 1
Work is a case of: Sl. No.		New Connectivity/Up gradation/ Maintenance Parameters to be checked		Remark
1.	Pavement	Tarameters to		
	Road Junction	condition		S/U
				\$ 5/11
b)	Condition of S			+
c)	Riding Quality	·	J. A.	S/U
d)	Road Camber		, , , , , , , , , , , , , , , , , , ,	S/U
c)	Whether free aggregates in c	from defects such ase of CC Payement.	as visible cracks, exposed	Yes/No
f)	Contraction Joints provided or not (CC Pavenich)			Yes/No
g)	Compaction of flank/slope & raincuts if and			Yes/No
2.	Cross Drainag	/	X	
a)	Condition of head walls in Humb pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing wall		Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Brid		Bridges	S/SRI/U
3.	Road Furniture			
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Payement road markings are provided and maintained			Yes/No
. (Compliance History			
S	Status of ATR's & any others			
	. •			
all Rating : Satisfactory (S)			5'	
	} —		ires Improvement (SRI)	۵
		Insatisfactory (U)	-	

Note, - out of maistenance.

(Signature)

NAME: Millish Kumar Liss
DESIGNATION: Junior Empirery Rexaul