Date of Inspection:				
Division: Balic	Length (km): 1.750			
Name of the Road: LO37-TO2 to Sandalpur (VR20)				
Scheme/Programme:	MAINTENANCE			
Package No.: BA-O	1R-238 Road Id No.: 32010602041			
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<b>v8/</b> Û
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	\8/TU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Wes/No
2.	Cross Drainage	Company of the second of the s
a)	Condition of head walls in Hume pipe culverts including its painting	√8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√8/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Executive Engineer RWD Works Division, Balia

NAME: Rameshwar choudhory DESIGNATION: Executive Engineer.