Date of 1	inspection: 16	6/12/20	District: Salarse	
Division: Scharps			Length (km): 1.50 Km	
	the Road:	and the second distriction of the second sec	Bhandarto S.IL-22	
-	Programme:	MAINTENANO		
Package	The state of the s	And the second second	Road Id No.: 209043008	40
	f the Project:		leted/Under Maintenance	
Work is	a case of:	And the second second	ity/Up gradation/ Maintenance	r say sandiya weki
SI No.	<b>在中国的</b>	Parameter	s to be checked	Remarks
71.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√s/U
d)	Road Camber			S/U
<b>c</b> )	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction o	Yes/No .		
2.	Cross Drains	ige		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			√S/SRI/U
-3	Road Furnite			
a)	Whether sign stones/Pavem	boards/informa	s are provided and maintained	Xes/No
$4\mu_{ij}$	Compliance	History		
a)	Status of ATE	L's & any others		

Overall Rating

Satisfactory (S)	$\bowtie$
Satisfactory but requires Improvement (SRI)	SRI

NAME: ASHOK KUMAR DESIGNATION: Executive Engineer