

FIELD INSPECTION REPORT

Date of Inspection :	16-12-2020	District:	W. Champaran
Division :	Nalhati	Length (km):	1.10 km
Name of the Road:	TO/ Sikarpur to Dakshin Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-441	Road Id No.:	31808902192
Status of the Project:	Ongoing/Completed/Under Maintenance under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-	
f)	Contraction Joints provided or not (CC Pavement)	S	
g)	Compaction of flank/slope & raincuts if any	S	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridges	S	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others	-	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

B. Kumar
16/12/2020
(Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.