FIELD INSPECTION REPORT

Companyor and the pit resource of majority pales and the companyor	- V 18	Tall B.	
Date of Inspection: 16.12.12020 District: Gaya:			
I APAY ACCURATE TO A CONTROL OF SUPERCONDUCTOR AND ACCURATE TO A CONTROL OTROL OF SUPERCONDUCTOR AND ACCURATE TO A CONTROL OF SUPERCONDUCTOR AND ACCURATE			
The second second second	Tthe Road: Lost - Gaya Tekan	good Tos to Do	eguna.
		MGSY	
	No.: BR-12R-676 Road I		
THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	f the Project: Ongoing/Completed/Under N		
Work is	a case of: New Connectivity/Up gradat	ion/ Maintenance	
SL No.	Parameters to be chec	ked	Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		\S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No >
g)	Compaction of flank/slope & raincuts if any		Yes/No
1	Grow Drainage		
a)	Condition of head walls in Hume pipe cult	verts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Sla		S/SRI/U
c)	Condition of railings/slab/approach for Br	idges	S/SRI/U

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

a)

8)

Road Furniture

Status of ATR's & any others

Satisfactory (S)		Edward Control of the
Satisfactory but requires Imp	rovement (SRI)	
Unsatisfactory (U)		

(Signature)

Yes/No

No

NAME:

DESIGNATION: E.E.