FIELD INSPECTION REPORT

| Date of Inspection: 18 12 2030 Division: Sheikhkena Name of the Road: Bishahiya Se Se Scheme/Programme: MAINTENANCE Package No.: | | | District: Sheikhpung | |
|--|--|---|-----------------------------|---------|
| Vame (| of the Road | Sevia | Length (km): / 200km | |
| Scheme | Programma: /3 | 2shahiya Se | Sanoriya Harrzan Tola | MMGSV |
| ackag | e No.: | MAINTENANCI | E | 40 |
| tatus | of the Project: | | | |
| Vork i | s a case of: | New Connectivity | ted/Under Maintenance | |
| | 医 | The W Connectivity | y/Up gradation/ Maintenance | |
| I) S | THE RESERVE OF THE PARTY OF THE | Parameters | to be eliceked | Remarks |
| a) | Payement Road Junction condition | | | |
| b) | Condition of Surfacing | | | VS/U |
| c) | Riding Quality | | | √8/U |
| d) | Road Camber | | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | S/U |
| f) | aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | -Xes/No |
| 2, | Cross Drainage | | | Yes/No |
| a) | Condition of head walls in Human | | | |
| b) | Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| c) | The state of the | Condition of railings/slab/approach for Bridges | | |
| 3 | Road Furnitu | C . | on for bridges | S/SRI/U |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m | | | |
| 4. | Compliance H | | re provided and maintained | Yes/No |
| a) | Status of ATR' | | 建设工程 | |

Overall Rating

| Satisfactory (S) | |
|---|--|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |
| | |

(Signature)

NAME: PANKAJ KUMAR

DESIGNATION: JE, Anen