

FIELD INSPECTION REPORT

Date of Inspection :	10/12/20	District:	East Champaran
Division :	Mithibari	Length (km):	0.799
Name of the Road:	To 4 to Arir tola via fule Babu tola		
Scheme/Programme:	MAINTENANCE (PMGSY)		
Package No.:	BR-11R - 609	Road Id No.:	-
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained. <i>Main board not in good condition</i>	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	- N/A -

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Prabir
10/12/20
(Signature)

NAME: Maheshwar Sharma

DESIGNATION: J.E.