## FIELD INSPECTION REPORT

Date of Inspection: 17/12/20		District: Halanda			
Division: Bilhay Shart			Length (km): 0,46716-		
Name of	the Road: SH 78	to Daulath	we to Raghermenthpur		
Scheme/	'rogramme: MA	INTENANCE	MABARS CRafya yoje	(Mu)	
Package			Road Id No.:		
	the Project: On	going/Completed	Under Maintenance		
	a case of: New Connectivity/Up gradation/ Maintenance  Parameters to be checked		Remarks		
Sl. No.		Parameters to		T 4	
1.	Pavement		The second secon	S/U	
ຸ - ຄ)	Road Junction condition			S/U	
b)	Condition of Surfacing				
c)	Riding Quality			S/U	
<u>d)</u>	Road Camber			S/U	
 	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)				S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SI			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			s/sri/u	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			MILL	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

17/12/20

(Signature)

NAME:

Birecel Kumar Single

DESIGNATION: J.B.

Scanned with CamScanner