

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District: MALANOLI
Division : Bicharkant		Length (km): 1.30 Km
Name of the Road: SH 78 to Mahabaleshwar Parnawan wadi		
Scheme/Programme: MAINTENANCE		MR-3054
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes, Not present
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
Compliance History		
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)
17.12.2020

NAME: Rana Basim Kumar Singh
DESIGNATION: Executive Engineer.

Scanned with CamScanner