

Latitude: 25.597557
Longitude: 84.399389
Elevation: 81.08 m
Accuracy: 7.5 m
Time: 12-19-2020 15:52
Note: Shahpur Banahi Chakarahi more hote Hetampur Ch 0.150Km

39

FIELD INSPECTION REPORT

old/MIR 3054

Date of Inspection: 19/12/2020		District: Bhojpur
Division: R.W.D. Jagdehpur		Length (km): 12.00 km
Name of the Road: Shahpur Banahi Chakarahi more Hote Hetampur		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 10401708061
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SRI ✓
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Remarks: Damaged RT surface at irregular intervals. CC pavement damaged in about 40m length. Some 200m stones are missing.

Rectification done or not: Not

NAME:

Rectification started or not: Not

Notice issued or not: Yes issued.

(Signature)

19/12/20

E E

(N.A. ISHRAT)