

FIELD INSPECTION REPORT

Date of Inspection: 18.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.71
Name of Road : 1032 T02 to Karakh		
Scheme / Programme: MAINTENANCE		PMGSV
Package No: BR-30R-512		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance


Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	R.I
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	NO S
f)	Constraction Joint provided or not(CC Pavement)	NO
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	H.A
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

S.R.I

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Ramesh Kumar S.B


 18.12.2020
 (Signature)

NAME:

DESIGNATION :

S.B