

# FIELD INSPECTION REPORT

Date of Inspection :	19/12/2020	District:	Nalanda
Division :	Harraut	Length (km):	1.0 km.
Name of the Road:	Gilanichak Pakargram Be. PINGSY Path to Bhojpur more		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition U	S/U
b)	Condition of Surfacing U	S/U
c)	Riding Quality U	S/U
d)	Road Camber U	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any NO	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained NO	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	✓

19/12/2020  
(Signature)

NAME: RAVI KUMAR

DESIGNATION: Sr. Engineer

Scanned with CamScanner