


FIELD INSPECTION REPORT

Date of Inspection:	District: SAMASTIPUR.
Division: RWD works Dhr Rosera	Length (km):
Name of the Road: 702 (L144) to Wm. Tola via Ching. MCSI	
Scheme Programme: MAINTENANCE	Road Id No.:
Package No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New/Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Compaction joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & talus if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m chains Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


(Signature) 17/12/20

NAME: **Ravi Shankar Kumar**
DESIGNATION: **Assistant Engineer, Shyamba**