

FIELD INSPECTION REPORT


Date of Inspection : 21.12.2020		District : E. Champaran
Division : Chakeria		Length (Km): 1.79
Name of the Road : L032 Rappur pwb road to Harijan Tola		
Scheme/Programme :		MAINTENANCE
Package No.: PMGSY		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'S'
c)	Riding Quality	'S'
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'S'
f)	Contraction Joints provided or not (CC Pavement)	'S'
g)	Compaction of flank/slope & raincuts if any	'U'
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	'S'
b)	Condition of Abutment & Wing walls, Slab In RCC Culverts	'S'
c)	Condition of railings/slab/approach for Bridges	—
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	'U'
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SR'
	Unsatisfactory (U)	

Note! - Some pots are generate due to flood and painting of board are damaged in this road

NAME :

DESIGNATION :


 21.12.2020
 J.E

(Signature)