FIELD INSPECTION REPORT

	ate of Inspection: 23/12/2000 District: Madhepura ivision: Madhepura Length (km): 3.42				
Divis					
		Timachhpus to MAINTENANCE	Husom		
-	ne/Programme:	IMAINTENANCE	Dood Id No. 03004700	80.0	
Package No.: Road Id I Status of the Project: Ongoing/Completed/Under Mai			Road Id No.: 21004700	8.20	
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.		Parameters to be checked		Remarks	
1,	Pavement				
a)	Road Junction	condition		S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free aggregates in o	Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No Was	kin progres
2.	Cross Drainag	ge			
a)	Condition of head walls in Hume pipe		culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls		, Slab in RCC culverts	S/SRI/U	
c)	Condition of ra	ilings/slab/approach for	r Bridges	S/SRI/U	
3.	Road Furniture				
а)	Whether sign stones/Pavemen	boards/informatory/cat t road markings are pro	ntionary Board/km & 200m ovided and maintained	Yes/No	
	Compliance History				
1)	Status of ATR's & any others				

Overall Rating

	at the same of
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SPI
Unsatisfactory (U)	

The agony has started the work. The rechibitation werk is in brogress. Warnington

(Signature)

NAME:

SANDTEV KUMAR

DESIGNATION:

EXECUTIVE ENGINEER

CE-3 Mr., RWD, Portra