


FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	District:	East Champaran
Division :	Pakhi dayal	Length (km):	0.600 Km
Name of the Road:	Dhuhauliya Malah Tola To P. M. G. S. Dhuhauliya Road		
Scheme/Programme:	MAINTENANCE	C. T. S. N. Y.	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
SL No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any.	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NA	


Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	


 (Signature)
 20/12/20
 A.E.

NAME:

DESIGNATION:


 Sanwar Alam
 S.E.


 19/12/20
 S.E.