## FIELD INSPECTION REPORT

Date of Inspection:	23112120	District:	East Chambaran	
Division: Monkola		Length (km):	4.269 KIM.	
Name of the Road: Lozg to Barkurwa				
Scheme/Programme:	MAINTENANCE /	PMOSY		
Package No.: BR-1	IR - 617	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			
SI. No.	Parameters to	be checked	Remarks	

SI. No.	Parameters to be checked	Remarks
1.	Pavement	to s
a)	Road Junction condition	<b>₩</b> 570
b)	Condition of Surfacing	\$/U
c)	Riding Quality	JS/TÚ
d)	Road Camber	<b>~\$</b> /U
- e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	¥es/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	marin war a
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/Ü
b) .	Condition of Abutment & Wing walls, Slab in RCC culverts	\S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
uncert had in	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	- M/A
a)	Status of ATR's & any others	EIIIN

Overall Rating

(0)	(5)
Satisfactory (S) Satisfactory but requires Improvement (SRI)	
	-
Unsatisfactory (U)	No. William

Screw Pile bildre approach danged due to Roan sain flood 2000 (Signature)

NAME: Makeshwar Sharma

DESIGNATION: J.E.