

FIELD INSPECTION REPORT

Date of Inspection: 19.12.20	District: Kachhar
Name of Road: crossing of chhabilal-tola Road to Earthen (Bind-tola Guvindpur botorzal)	
Scheme/ Programme: MAINTENANCE	
Package No. —	Road ID No. —
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/ Up Gradation/ Maintenance	

SLNo	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	— S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	— S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	— S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	✓Yes/No
4	Compliance History	
a)	Status of ATR & any others	NO

Overall Grading:	S
Satisfactory (S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name: SHIV HANAYAN HANADAL
 Designation: AE RWS (U) Sub Div Andakbar

Signature: SHIV HANAYAN HANADAL
 19.12.20