

FIELD INSPECTION REPORT

Date of Inspection :	26.02.2020	District :	Lakshisarai
Division :	Lakshisarai	Length (Km) :	8.8 km (Wade down 7.6 km)
Name of the Road :	Repair of road from NH-80 Mitthi Bhatla to Akharpur		
Scheme/Programme :	MAINTENANCE MR (S+U) 011		
Package No. :		Road Id No. :	20804000827
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	Pots drilled up with material.
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Approach near EEC Culvert facing road has longitudinal cracks. It is visible. It is Tal Area & floodwater is there.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its pointing	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	Approach damaged.
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Km 8.200 Missing
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME : RAJIV RANJAN KUMAR
DESIGNATION : EE

Ranjan Kumar
(Signature)