

FIELD INSPECTION REPORT

Date of Inspection : 22-12-2020 District : East Champaran

Division : Bhojpur (w) Chokim

Length (Km) : 1.100

Name of the Road : Beryati Bani House to Brijm Baniha To1

Sub-division / Range / Section :

MAINTENANCE

Package No.:

Road ID No.:

Status of the Project

Ongoing/Completed/Under Maintenance

Work is a case of

New Connectivity/Up Gradation/ Maintenance

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction joints provided or not (CC Pavement)	Yes
g)	Compaction of Bank/slope & re-cuts if any	S
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign board/Informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

S

[Signature]
22/12/2020
(Signature)

NAME : C. L. Choudhary P. Virmo

DESIGNATION : A-E