

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 2716

दलसिंहसराय/दिनांक 22/12/2020

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान **Rs.-33.44800 (Thirty Three Lakh Forty Four Thousand Eight Hundred Rupess)** कि आवश्यकता है अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-33.44800 (Thirty Three Lakh Forty Four Thousand Eight Hundred Rupess)** उपलब्ध कराने की कृपा की जाये।

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फ़ॉर्म।
3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन

(Signature)
22-12-2020

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

(Signature)
22-12-2020

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1		T02 to Muslim Tola	32010302075		1.200	41.91590	22.85800	10.67871		16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
2		NH-28, Satampur to REO Road Satampur	32010401004		2.050	75.67490	41.81000	19.70644		16.09.2020	-	3417	25mm	5.10%	0.00000	0.00000	33.44800	
3		Repair of Road from Madya vidayya Ujijarpur se Munial Mahito ke ghar hote hue ujijarpur station ke dakhini gunti tak	32010401021	2200 / 08.07.2019	1.270	39.66150	21.36400	11.46792	65 MBD/2019-20/21.01.2020	16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
4		Repair of Road From Ujiaarpur Railway Gumati NO 44 to Dhamua Tola via Rampur Ekshila	32010405011		0.900	26.33390	14.53700	7.37648		16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
5		MDR Malvi	NEA220001093		2.000	71.05010	37.94600	19.08506		16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
					7.420	254.636	138.51500	68.31461							0.000	0.000	33.44800	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

- 1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
2 Up-to date Physical Progress has been uploaded in MIS.

Sr Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)

Form of Utilisation Certificate upto December 2020

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	457.38141	457.38141	Certified that out of Rs-457.38141 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-457.38141 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-0.00 Lakh remaining unutilized at the end of period under the time of completion
		457.38141	457.38141	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was


Kind of Checks Exercised:-


- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved


- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai



Ramulata
22-12-2020

File : C:\MYNew folder\New folder\22121824.Xls, Section No. : 82, Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$
Name of Customer : Sona Infraeco Pvt Ltd, Name of Work/ Road : NH-28, Satapur to REO Road Salampur, Lab Job



Handwritten signature
17/11/17

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5		
17/ 12/ 20	12: 51: 52	82	0.1	380	0	3800	3500	A	0	0	Curve	X = 4200		
17/ 12/ 20	12: 53: 40	82	0.1	240	0	2400	2858	G	25.75398	85.77978	Normal	Y = 4903		
17/ 12/ 20	12: 54: 14	82	0.1	410	0	4100	3400	A	25.753188	85.779393	Curve			
17/ 12/ 20	12: 55: 0	82	0.1	470	0	4700	3200	P	25.752453	85.778803	Curve			
17/ 12/ 20	12: 55: 25	82	0.1	250	10.1	2500	2972	G	25.751918	85.778047	Normal	(R) RURAL ROAD		
17/ 12/ 20	12: 56: 0	82	0.1	250	10.1	2500	2972	G	25.751358	85.777288	Normal	Good		
17/ 12/ 20	12: 56: 35	82	0.1	240	10.1	2400	2858	G	25.75071	85.77668	Normal	<4000	Average 4001-5000	Poor >5001
17/ 12/ 20	12: 57: 0	82	0.1	360	10.1	3600	3800	A	25.749893	85.776413	Curve			
17/ 12/ 20	12: 57: 11	82	0.1	480	10.1	4800	3600	P	25.748995	85.776178	Curve			
17/ 12/ 20	12: 58: 0	82	0.1	350	10.1	3500	3200	A	25.748272	85.775655	Curve			
17/ 12/ 20	12: 58: 21	82	0.1	350	10.1	3500	3500	A	25.747562	85.77507	Curve			
17/ 12/ 20	12: 58: 21	82	0.1	400	10.1	4000	3600	A	25.747552	85.774175	Curve			
17/ 12/ 20	12: 59: 0	82	0.1	290	10.1	2900	3100	G	25.746998	85.773787	Normal			
17/ 12/ 20	13: 0: 0	82	0.1	310	0	3100	3200	G	25.746232	85.77382	Normal			
17/ 12/ 20	13: 0: 7	82	0.1	440	10.1	4400	2950	P	25.745393	85.773535	Curve			
17/ 12/ 20	13: 1: 0	82	0.1	410	10.1	4100	3800	A	25.74458	85.773232	Curve			
17/ 12/ 20	13: 1: 18	82	0.1	340	0	3400	3994	G	25.743707	85.772793	Curve			
17/ 12/ 20	13: 2: 0	82	0.1	320	10.1	3200	3767	G	25.742868	85.772473	Normal			
17/ 12/ 20	13: 2: 28	82	0.1	430	10.1	4300	3900	P	25.74207	85.772053	Curve			
17/ 12/ 20	13: 3: 3	82	0.1	510	10.1	5100	3800	P	25.741268	85.771598	Curve			
17/ 12/ 20	13: 4: 14	82	0.1	710	0	7100	3800	P	25.74052	85.771093	Curve			



 17/12/20