

FD R (2020-21) N13410-24  
Schedule XLV-Form No. 134

Nigeria's access to well  
ground path

DIVISION

Black - Dham doka

SUB-DIVISION

Measurement Book

Name to work—  
 Situation of work—  
 Agency by which work is executed—  
 Date of measurement—  
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

| Particulars                                                                         | Details of actual measurement |    |    |    | Contents of area |
|-------------------------------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                                                     | No.                           | L. | B. | D. |                  |
| NAME of work: Restoration of Bridge Approach Mingant Sani Road to Bela Ground Path. |                               |    |    |    |                  |
| Authority: E.E.R.W.D                                                                |                               |    |    |    |                  |
| Works Division, Dhamdaha.                                                           |                               |    |    |    |                  |
| 1- Supply, fitting and fixing of Bamboo (62 mm to 75 mm) dia                        |                               |    |    |    |                  |
| B x 50 = 400 Miter.                                                                 |                               |    |    |    |                  |
| 2- Labour for driving                                                               |                               |    |    |    |                  |

|                                                     |  |  |  |  |  |
|-----------------------------------------------------|--|--|--|--|--|
| (62 mm to 75 mm)                                    |  |  |  |  |  |
| dia Bamboo Piles                                    |  |  |  |  |  |
| 15.0 Miter length = 667 Miter.                      |  |  |  |  |  |
| 3- Supply, fitting and fixing Bamboo woven chanchay |  |  |  |  |  |
| 50 Miter x 15 Miter = 75 M <sup>2</sup> .           |  |  |  |  |  |
| 4- Supply and Spreading of Brick Bats               |  |  |  |  |  |
| 900 Miter. 5.0 M x 3.50 Miter                       |  |  |  |  |  |
| x (0.80 + 0.90) m                                   |  |  |  |  |  |
| 2 = 14.88 M <sup>3</sup>                            |  |  |  |  |  |
| 7 M x 3.50 M x (0.80 + 0.90) m                      |  |  |  |  |  |
| = 20.82 M <sup>3</sup>                              |  |  |  |  |  |
| Continuation T - 35.71 M <sup>3</sup>               |  |  |  |  |  |

PICUMDA  
30-11-20  
(J.E.)

~~30-11-20~~

30-11-20

Executive Engineer,  
Rural Works Department  
Works Division Dhamdaha (Burela)

Scanned by CamScanner

Bf-1, B-1, B242

| Particulars | Details of actual measurement |                   |        |    | Contents of area |
|-------------|-------------------------------|-------------------|--------|----|------------------|
|             | No.                           | L.                | B.     | D. |                  |
|             |                               | 62 mm             | 675 mm |    |                  |
|             |                               | dia 400 Mtr       |        |    |                  |
|             |                               | or P-01 item      |        |    |                  |
|             |                               | (01) cals.        |        |    |                  |
|             |                               | 4: 59/1 mtr       |        |    |                  |
|             |                               |                   |        |    | 1836-            |
|             |                               |                   |        |    |                  |
| 5/5         |                               | supply fitting    |        |    |                  |
|             |                               | and fixing bamboo |        |    |                  |
|             |                               | Chanchang 75 M    |        |    |                  |
|             |                               | or P-01 item      |        |    |                  |
|             |                               | No. (05) or U-    |        |    |                  |
|             |                               | 22 1: 69/1 M2     |        |    |                  |
|             |                               |                   |        |    | 16.6272          |
|             |                               |                   |        |    | 2,00,2872        |

|               |   |           |
|---------------|---|-----------|
| Add 12% C.S.T | — | 24,0242   |
| Add 1% L.C.A. | — | 20022     |
| Add S. Fee    | — | 10,1002   |
| Total         |   | 2,36,4242 |
|               |   | 2,36,4242 |

From  
26-02-2021  
(50)

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs-

Dhamdaha.

2. Name of Block/Road-

Mirganj Sassi Road To Bela Kodidh Path.  
(Bridge Approach)

A. For Road

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

27.00m

Side and Top of the surface damage due to flood.

Brick Bat.

Tractor

Manual

27.00m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration


ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length


Signature of JE/AE/EE

  
28/1/21

  
28.01.21

Signature

(Name of Inspector)

  
28/1/21