

FD R (2020-21) MB.No - 31
Schedule XLV-Form No. 134

Lost to Kulkarny To G No - 1

DIVISION

Blank - **SUB-DIVISION**

Measurement Book

1

PgU

Nurn
-ock

3

1

•

$13.40 \text{ m} \times \frac{(2.40 + 3.60) \text{ m}}{2}$
 $\times \frac{(1.20 + 1.50 + 0.90) \text{ m}}{3}$
 $= 48.24 \text{ m}^3$
 $9.20 \text{ m} \times \frac{(1.80 + 3.20) \text{ m}}{2}$
 $\times \frac{(1.30 + 1.80 + 1.10) \text{ m}}{3}$
 $= 32.20 \text{ m}^3$
 $T = 119.02 \text{ m}^3$
 Kuman
 29-11-2020
 (J.E.)
 30/11/20
 GVS
 29.11.20

~~day~~
30/11/20
Gru

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(ABSTRACT OF COST)					
1/1 Providing Brick					
Ball spreading					
and supply etc.					
110.02 m ² or 8.04					
Item No (01) @					
Rs. 1717.37 /-					
					Rs. 20440/-
Add 12% (n) S.T. —					(Rs) 24528/-
Add Labour cell 1/1 —					(Rs) 20442/-
Add S. Fee —					(Rs) 1126002
					Total Rs. 2,43,5732
					Rs. 2,43,5732
Final					
26-02-2021					
Signature					

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- LO57 to Kulkoon Tola No-I

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 36.80 m

3. Nature of Damage : Slope damage due to flood.

4. Details of Restoration :

i Material being used in Restoration : Bank Bats

ii Equipment/Tools being used in Restoration works: Tractor

iii Procedure taken up in Restoration works : Manual

iv Restored Length : 36.80m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Pruma
27-01-2021

Signature of JE/AE/EE

27/1/21
EE

27-1-21
EE

Signature

(Name of Inspector)