

FDR (2020-21) N.B. No - 29

Schedule XLV-Form No. 134

मिळिया मया तले ते मिल्किया

मार्ग रोड.

DIVISION

SUB-DIVISION

Black - Phamdahq.

Measurement Book

Name to work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

1

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK - Restoration of Road Milkia Naya Tola to Milkia Main Road.					
Authority - E. E. R. W. D.					
WORKS Division, Dharmachakra					
1 - Supply, fitting and fixing of Bamboo 62 mm to 75 mm dia					
B x 243.0 Mtr - 1944					Mtr.
2 - Labour for driving					

62 mm to 75 mm				
Bamboo piles.				
72.0 M Length = 243.0 Mtr.				
3 - Fitting and fixing in position Bamboo woven chanchary				
243 M x 1.50 m = 364.5 M ² .				
4 - Supply and spreading of Brick Rats				
C/H - 200 M				
L/S - 5 M x (1.40 + 1.95) m				
		2		
X (0.50 + 0.60) m = 4.62 M ²				
		2		

Continuation - 4.62 M²

B/F - 4.6 LM³

Sch. XLV—Form No. 134

2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2.60 M x (1.55 + 2.25) M		2			
x (0.90 + 0.50) M		2			3.46 M ³
300 M - 1/5 - 73 M x (1.58 + 2.33)					
x (0.60 + 0.80 + 0.90 + 0.70) M		4			
					= 107.04 M ³
R/S - 32 M x (1.48 + 2.25) M		2			
x (0.90 + 0.80 + 0.60) M		3			= 45.75 M ³
R/S - 42 M x (1.63 + 2.49) M		2			

x (0.70 + 1.0 + 0.90) M		3			= 73.20 M ³
Total - 234.06 M ³					

Priman
29-11-2020
(J.E)

~~234.06~~
234.06

29.11.20
Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Pune)

Continuation

Sch. XLV—Form No. 134				3	Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
(ABSTRACT OF COST)					
1/1 Providing and spreading brick ball	236	06	M ²		
by P. 02 item					
(01) @ Rs.					
22	1269	M ²			
1717 = 37/11					Rs. 405402.
2/2 Labour for driving					
62 mm x 75 mm					
dia 3240 miter					
by P. 02 item					
N. (02) @ Rs.					

26 = 35	miter			Rs. 85374
3/3 supply, fitting and fixing of				
Bamboo 1944				
miter by P. 01				
item No. (01) @				
Rs. 4259				
miter				Rs. 89232.
4/4 supply and spreading				
of brick ball 304.5 M ²				
223406 M ² on P. 02 item				
No. (04) @ Rs.				
22	1269	M ²		Rs. 808062
Continuation Rs. 5,80,50520				

[illegible]

Scanned with CamScanner

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha.

2. Name of Block/Road- Mikiya Naya Jola to Mikiya Main Road

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 177-88m

3. Nature of Damage : Both side slope damage due to flow

4. Details of Restoration :

i Material being used in Restoration : Barbed wire

ii Equipment/Tools being used in Restoration works: Tractor

iii Procedure taken up in Restoration works : Mahua

iv Restored Length : 177-88m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Praveen
28-01-21
Signature of JE/AE/EE

28/1/21
28

28-1-21
E

Praveen
28/1/21
Signature
(Name of Inspector)