

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 31/7/21	District: Serran
Division : Chapra-2	Length (km): 3.69
Name of the Road: 622 Bhairanpur Ki Dhouri to Chhapra, Part I	
Scheme/Programme: PMASy	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A.
c)	Condition of railings/slab/approach for Bridges	N.A.
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	ATR Submitted at S.R. R.W.D. P.M.
a)	Status of ATR's & any others in maintenance	U

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Bindu Pasak

Designature:-

Executive Engineer

R.W.D. Regional Lab. Darbhanga

(Signature)

31/7/21