

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 31/7/21	District: Sonam
Division : Chapra-2	Length (km): 2.687
Name of the Road: Lohar to Saran (VR 33)	
Scheme/Programme: PMGSY	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	BE Chapra-2 ATR send to S.D.C R.W.D. from 25.07.21 vide letter No 25 dt-05/01/21
a)	Status of ATR's & any others	in maintenance U

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Bindu Rajak
Executive Engineer
R.W.D.

Designature:-

Regional Lab Dars Bhanger

(Signature)

31/7/21