## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Division	Inspection: 81/7/21 District: Serran  1: Chapra-2 Length (km): 0.70  f the Road: SH Mashrakh cold Storage toupto Del	Doyila Bhavsa
Scheme/Programme: MMGSY (Cron.) Smyth 120 tola		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	5
b)	Riding Quality	2
· c)	Road Camber	2
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- N.Y.
e)	Contraction Joints provided or not (CC Pavement)	N.H
f)	Compaction of flank/slope & raincuts if any	2
B	ation Remarks: - Croass & Spreading on the road	
2.	Cross Drainage	14:3
a)	Condition of head walls in Hume pipe culverts including its painting	9
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N. A
c)	Condition of railings/slab/approach for Bridges	N. A
d)	Condition of Vent Clearance	3
Observation Remarks:-		
3.	Road Furniture	198
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Designature:-

Binda Rajak Executive Engineer Dio:D' Cab. Dasbhanga Regional Cab. Dasbhanga

अमिनिह.

J31721

(Signature)